

Thermometer Manual

ST-18

Description of Button Functions

- a. ON/OFF Button: Press the button to power on/off the meter. The meter will automatically power off in 15minutes on inactivity.
- b. HOLD Button: Press the HOLD button momentarily to enter in the Data Hold mode; keep pressing the HOLD button to enter into the MAX/MIN mode.
- c. °C / °F Button: When the LCD displays a temperature, press to change display from °C to °F